FEEBOOK: 2006 4637 12/14/2006 10:24 AM

**REC FEES: \$7.00** 

PAGES: 1

## Marie Krutzfield, Recorder Jones County, Iowa

1540 MIDLAND COURT NE CEDAR RAPIDS, IOWA 52402

(319) 294-9424

366106-10

PREPARED BY

STEPHEN MICHAEL BRAIN, BRAIN ENGINEERING, INC., 1540 MIDLAND COURT NE, CEDAR RAPIDS, IOWA PH. (319) 294-9424

## TINITOTO STATES DIDITE LAND

SURVEY CORNER CERTIFICATE					
LAND SURVEY MONUMENTS SITUATED IN RANGE _4_ WEST OF THE 5TH P.M., _	SECTION <u>10</u> , TOWNSHIP <u>84</u> NORTH JONES COUNTY, IOWA.				
NO SCALE  SW CORNER  SE 1/4 SW 1/4  10	NO SCALE				
FOUND "X" NAILS FENCE POST  10.40'  SET "X" NAILS CORNER POST  SET "X" NAILS IN 18" OAK					
PREVIOUSLY RECORDED IN BOOK PAGE MONUMENT DESCRIPTION AND HOW ESTABLISHED FOUND 5/8" REBAR.	PREVIOUSLY RECORDED IN BOOK PAGE  MONUMENT DESCRIPTION AND HOW ESTABLISHED				
I hereby certify that this land surveying document and the related survey work was performed by me or under my direct personal supervision and that I am a duly licensed Land Surveyor under the laws of the State of lawa.  Stephen Michael Brain, L.S.  My License Renewal Date is December 31, 2006  License Number 9647  Pages or sheets covered by this seal: 1/1  CORNERS TO BE INDEXED	□ A.THERE IS NO CERTIFICATE FOR THE CORNER ON FILE     WITH THE RECORDER OF THE COUNTY IN WHICH THE     CORNER IS LOCATED      □ B.THE SURVEYOR IN RESPONSIBLE CHARGE OF THE LAND     SURVEYING ACCEPTS A CORNER POSITION WHICH DIFFERS     FROM THAT SHOWN IN THE PUBLIC RECORDS OF THE     COUNTY IN WHICH THE CORNER IS LOCATED.      □ C.THE CORNER MONUMENT IS REPLACED OR MODIFIED IN     ANY WAY.      □ D.THE REFERENCE TIES REFERRED TO IN AN EXISTING     PUBLIC RECORD ARE NOT CORRECT.				
CORNER SECTION TOWNSHIP RANGE SW CORNER 10 T84N R 4 W SE 1/4 SW 1/4	BRAIN ENGINEERING, INC.  1540 MIDLAND COLIFT NE				

SECTION CO	ORNER C	ERTIFIC	ATE	
LAND SURVEY MONUMENTS SITUATE RANGE 4 WEST, OF THE FIFTH P				
PREVIOUSLY RECORDED IN BOOK _	AT PAC	E	FOR REC	ORDER'S USE
REASON FOR PREPARING CERTIFICATE:  A) THERE IS NO CERTIFICATE FOR THE CORNER OF THE COUNTY IN WHICH THE CORNER IS  CORNER POSITION DIFFERS FROM THAT SHOOF THE COUNTY IN WHICH THE CORNER.IS  C) THE CORNER MONUMENT HAS BEEN REPLACED TO IN AN INCORRECT.	LOCATED.  DWN IN THE PUBLIC LOCATED.  CED OR MODIFIED.	RECORDS		
MONUMENT DESCRIPTION AND REMARKS  N.E. CORNER N.W. 4- N.W. 4 SE	<u>.</u> CTION 15-84	-4 FOUR	10 58" \$ R	'EBAR
4" ABOVE GROUND INSIDE OF N'4 CORNER FOUND R.H. IN TOP ALONG EAST SIDE OF CORN	CORNER POIT  OF CORNER			
RECOVE	RY TIE D	RAWING		
N.E. COR NW4-N.W. 4 15-84-4		N'4 Cor	. 15-84	- 4
MCAEU = 0.9=  MOTOR = 0.0=  MO	NOT TO SCALE	8". 8".	16:35 14 27 14 27 14 16 16 16 16 16 16 16 16 16 16 16 16 16	R.H. IN BRACE POST  SET 2  REBAR  R.H. IN 15t  STEEL FR. POST
GLEN D. MEISNER L.S. NO 8165 DA	Y DIRECTION AND OF RECORD IS CORF	CONTROL AND	LETE !	GLEN D. MEISNER 8165
Solve Tee Pin Set U.S. PUBLIC LA			226 29TH CEDAR RA 319	ALL ENGINEERS, INC STREET DRIVE S.E. PIDS, IOWA 52403 -362-9548
NR.W.B. KG.D.M.	12-18-92	NONE	FNº PN R OT 23. 0	4550