

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

Land Survey Monuments situated in Section 21, Township 84N, Range 4W, of the Fifth Principal Meridian, Jones County, Iowa. Previously recorded in ___SEE_NOTE__ in the Office of the County Recorder Monument Description and Remarks: SE CORNER - FD. 1/2' IRON ROD IN CONCRETE MONUMENT E1/4 CORNER - FD. 1/2' IRON ROD IN CONCRETE MONUMENT NOTE - THE SE CORNER WAS PREVIOUSLY TIED AND RECORDED IN FILE NO. 2002 3629 PLAN VIEW SE CORNER E1/4 CORNER SET NAIL W/ WITNESS DISK CORNER POST WEST BOUND LANE #151 FD. 1/2' IRON ROD IN CONCRETE MONUMENT 40,684 56.68, 65,29 -FD, 1/2″ IRON ROD IN CONCRETE MONUMENT 65.78 90TH ST. 57.34 39.24 BOUND LANE #151 EAST 'X' NAILS FD. CUT 'X' IN EDGE CONCRETE SLAB AT ALL TIE POINTS



CORNERS TO BE INDEXED

SE CORNER E1/4 CDRNER




I hereby certify that this land surveying document was prepared and related survey work was performed by me or under my direct personal supervision and that I am a duly licensed Land Surveyor under the laws of the State of Iowa.

William H. Burger

License number 12642

My license renewal date is December 31, 2012 Pages or Sheets covered by this seal Sheet 1 of 1


(Show a infolmation of three reference lies to durable physical objects, relevant monuments and physical conditions that all enable recovery of the corner.)



ALL DISTANCES

SLOPE CHANED

135 -844240.090204.+26



Thereby certify that the survey work was completed and this aertificate was prepared by one or under my direct personal supervision and that I am a duly registered land surveyor under the laws of the state of lowe.

LAND CORNERS TO BE RECORDED

Corners E 1/4

Section Two

Range

ŵ.

Signature:

MANCHESTER COUST

08\02\04 4W

FROM IDOT 9-02-04

0

SECTION CORNER CERTIFICATE						
LAND SURV RANGE <u>4</u>	EY MONUMENTS WEST, OF THE	SITUATED FIFTH PRIN	IN SECTION_ ICIPAL MERID	21. TOWNSH IAN, <u>Jones</u>	IIP <u>84</u> , COUNT	_NORTH, Y, IOWA.
PREVIOUSLY	RECORDED IN	воок	AT PAG	E	FOR REC	ORDER'S USE
REASON FOR PREPARING CERTIFICATE: A) THERE IS NO CERTIFICATE FOR THE CORNER ON FILE WITH THE RECORDER OF THE COUNTY IN WHICH THE CORNER IS LOCATED. B) CORNER POSITION DIFFERS FROM THAT SHOWN IN THE PUBLIC RECORDS OF THE COUNTY IN WHICH THE CORNER.IS LOCATED. C) THE CORNER MONUMENT HAS BEEN REPLACED OR MODIFIED. THE REFERENCE TIES REFERRED TO IN AN EXISTING PUBLIC RECORD ARE INCORRECT.						
MONUMENT DESCRIPTION AND REMARKS :						
W'14 Found Conc. Mon. w 1/2" Pin 8" above ground E'14 Found Conc. Mon broken, County Engr. ties						
E'14 Found Conc. Mon broken, County Engr. ties						
RECOVERY TIE DRAWING						
Pin in cone. E/4 Co D.M. 9/18/31	p in	onc	NOT TO SCALE	4	Highway Br	15/ TOKEN CONC. 28 (5 Mon. 162 Pipe Notch In TOP Pipe RNER POST
GLEN D. MEISNER COVERNMENT CORNER CO 5/8" TIE PIN SET CONTRACTOR CONTRACTO	PROJECT THE U.S. PU	R UNDER MY I Y MONUMENT I D BELIEF. 55 DATE JBLIC LAN	DIRECTION AND RECORD IS CORE 29-91 ND SURVEY	CONTROL AND RECT AND COMP	HALL AND 226 29TH CEDAR R 31	HALL ENGINEERS, INC. I STREET DRIVE S.E. APIDS, IOWA 52403 9-362-9548
N GDA) 법	P	D A T E)	44.85