



01 DEC 26 PM 12:10

MARIE KRUTZFIELD
RECORDER 6.00 Pd

PREPARED BY THOMAS ANTHONY, 535 SOUTHGATE Ave. IOWA CITY, IA 52240, 319-354-1984

JONES COUNTY U.S. PUBLIC LAND SURVEY CORNER CERTIFICATE																	
	<p>All ties are double head nail w/ disc #8295</p> <p>Broken Brace post (No tie)</p> <p>E. face End post</p> <p>0.42' to NE face Corner post</p> <p>E. face Brace post</p>																
<p>Monument Description and Remarks:</p> <p>NW 1/16 Section 36-83-03 Set 5/8" rebar w/ cap 8295 at midpoint of 1/4 line. Falls in \angle of road.</p>	<p>Monument Description and Remarks:</p> <p>NW 1/16 Section 36-83-03 Dug & probed near corner post - no stone. Set 5/8" rebar w/ cap 8295 on E-W 1/4 1/4 line at N-S 1/4 1/4 fence line.</p>																
<p>I hereby certify that this land surveying document was prepared and the related survey work was performed by me or under my direct supervision and that I am a duly licensed Land Surveyor under the laws of the State of Iowa.</p>																	
 <p><u>Thomas Anthony</u> 12-24-2001 Thomas J. Anthony date License number 8295 My license renewal date is December 31, 2002. Pages or sheets covered by this seal: 1 of 1</p>																	
 <p>LANDMARK Surveying and Engineering 535 Southgate Avenue Iowa City, Iowa 52240 Phone (319) 354-1984</p>	<table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th>Corner</th> <th>Section</th> <th>Twp</th> <th>Range</th> </tr> </thead> <tbody> <tr> <td>NW 1/16</td> <td>35</td> <td>83</td> <td>03</td> </tr> <tr> <td>NW 1/16</td> <td>35</td> <td>83</td> <td>03</td> </tr> </tbody> </table> <table border="1" style="width:100%; border-collapse: collapse; margin-top: 5px;"> <tr> <td>Field Bk 87/11</td> <td>Date 5/2/01</td> <td>Job No. 6.99016B</td> <td>Sheet 1 of 1</td> </tr> </table>	Corner	Section	Twp	Range	NW 1/16	35	83	03	NW 1/16	35	83	03	Field Bk 87/11	Date 5/2/01	Job No. 6.99016B	Sheet 1 of 1
Corner	Section	Twp	Range														
NW 1/16	35	83	03														
NW 1/16	35	83	03														
Field Bk 87/11	Date 5/2/01	Job No. 6.99016B	Sheet 1 of 1														

I, Thomas Anthony, depose and state as follows:

1. That I am a duly Licensed Land Surveyor licensed and practicing in the State of Iowa, with License Number 8295 renewable December 31, 2002; and
2. That I executed a survey of and supervised the preparation of certain Section Corner Certificates which were recorded December 26, 2001, as DOCUMENT NO. 2001-4537, 4538 and 4539, Jones County Recorder's Office; and
3. That a scrivener's error has been detected on said certificates and in accordance with the provisions of Chapter 354.24, Code of Iowa, the following correction should be substituted for the erroneous data on said certificates:
 - A. In the box on each certificate labeled "Monument Description and Remarks", the section number is mistakenly stated as 36 when in fact Section 35 is correct as stated elsewhere on each certificate.
4. That the correction stated herein does not affect the locations of the boundaries or the areas depicted on the related plat recorded in Plat Book O - Page 139.

Dated this 8th day of January, 2002.