## THIS IS NOT A CERTIFICATION

JONES COUNTY ENGINEER'S OFFICE, 19501 HWY. 64, ANAMOSA, IOWA, 52205 (319)462-3785

## UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

LAND SURVEY MONUMENTS SITUATED IN SECTION 4, TOWNSHIP 82 NORTH, RANGE 3 WEST OF THE 5TH P.M., JONES COUNTY, IOWA

CORNERS TO BE INDEXED	CODNEDC TO DE INDEVED
CORNER SECTION TOWNSHIP RANGE N-QUARTER 4 82N 3W	CORNERS TO BE INDEXED  CORNER SECTION TOWNSHIP RANGE  OFFICE FILE NO.
	NO SCALE
### 192003  JONES COUNTY REF:  LC—714 BK. 316 P 45  10—12—92  JONES COUNTY  CONC. POST	5/4-33-83-3 83333w_122203
CEDAR-JONES COUNTY ROAD	
CEDAR COUNTY LINE  CEDAR COUNTY,  65.15  65.15  CEDAR COUNTY LINE  SOLUTION AND COLUMN A	601
REDS TOP WOOD POSTS	
PREVIOUSLY RECORDED IN BOOK, PAGE_ MONUMENT DESCRIPTION AND HOW ESTABLISHED 10-12-92 COUNTY SURVEY CREW INDICATED 5/8"X24" IRON PIN 12" BELOW SURFACE. SET REFERENCE POINTS AND TIED OUT AS INDICATED. NORTH QUARTER CORNER SECTION 4, TOWNSHIP 82 NORTH, RANGE 3 WEST OF THE 5TH PRINCIPAL MERIDIAN, JONES COUNTY, IOWA.	PREVIOUSLY RECORDED IN BOOK, PAGE MONUMENT DESCRIPTION AND HOW ESTABLISHED
CORNERS TO BE INDEXED	CORNERS TO BE INDEXED
CORNER SECTION TOWNSHIP RANGE	CORNER SECTION TOWNSHIP RANGE
OFFICE FILE NO.	OFFICE FILE NO.
PREVIOUSLY RECORDED IN BOOK, PAGE MONUMENT DESCRIPTION AND HOW ESTABLISHED	PREVIOUSLY RECORDED IN BOOK, PAGE MONUMENT DESCRIPTION AND HOW ESTABLISHED
hereby declare that this plat, survey or repo was made by me or under my direct personal supervision and that I am a duly registered Lo Surveyor under the laws of the State of Iowa.	ENGINEER'S OFFICE
Signed:	19501 HWY. 64, ANAMOSA, IOWA, 52205 (319)462-3785
-	

SECTION CORNER CERTIFICATE			
LAND SURVEY MONUMENTS SITUATED IN SECTION <u>28</u> , TOWNSHIP <u>83</u> NORTH, RANGE <u>3</u> WEST, OF THE FIFTH PRINCIPAL MERIDIAN, <u>Jones</u> , COUNTY, IOWA.			
PREVIOUSLY RECORDED IN BOOK		FOR RECORDER'S USE	
REASON FOR PREPARING CERTIFICATE			
A) THERE IS NO CERTIFICATE FOR THE CORNER ON FILE WITH THE RECORDER OF THE COUNTY IN WITCH THE CORNER IS LOCATED.			
B) CORNER POSITION DIFFERS FROM THAT SHOWN IN THE PUBLIC RECORDS OF THE COUNTY IN WHICH THE CORNER IS LOCATED.			
☐ C) THE CORNER MONUMENT HAS BEEN REPI ☐ CO THE REFERENCE TIES REFERRED TO IN INCORRECT.	ACED OR MODIFIED.	D ARE	
MONUMENT DESCRIPTION AND REMARKS:			
SW CORNER - FOUND 5/8' IRON PIN BURIED 6' DOWN FROM PREVIOUS TIES. S 1/4 CORNER- DUG ON FENCE LINE NORTH FOUND 18"x 10"x 24" GRANITE STONE			
REMOVED STONE FOUND PIECES OF WOOD STAKE LINDER STONE REPLACED STONE			
AND PLACE 5/8"x 18" IRON PIN ABOVE STONE BURIED 1' BELOW SURFACE.			
RECOVERY TIE DRAWING			
SW COR. SEC 33 T83N R3W	R-3W	1/4 COR SEC 33 T83N R3W	
red top wood post  99.75'  Sel Iron pin Buried 6'  27.4'  13.20  Cedar  County corner  Distance slope meas.  CERTIFICATION  I.GLEN D. MEISNER. — CERTIFY THAT	NOT TO SCALE	x' top Conc. Post  5/8' iron pin above stone  31.75  Reds Top Wood Posts  ance slope neas.  1.75 ON CARD M.S.	
I,GLEN D. MEISNER, — CERTIFY THAT THE CORNER LOCATION(S) SHOWN ON THIS RECORD WERE DETERMINED BY ME OR UNDER MY DIRECTION AND CONTROL AND THAT THIS U.S. PUBLIC LAND SURVEY MONUMENT RECORD IS CORRECT AND COMPLETE 8165  TO THE BEST OF MAY KNOWLEDGE AND BELIEF.    D. M. D. M. D. M. D. M. B. D. D. D. B.			
△ GOVERNMENT CORNER TITLE IIC C DIIDI IC		CORD H HALL AND HALL ENGINEERS, INC.	
O 5/8" X 30" W/ LS. CAP SET TO		226 29TH STREET DRIVE S.E. CEDAR RAPIDS, IDWA 52403	
RDV C R	P	319-362-9548 Re	