
## UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

LAND SURVEY MONUMENTS SITUATED IN SECTION 35, TOWNSHIP 83 NORTH, RANGE 3 WEST OF THE 5TH P.M., JONES COUNTY, IOWAS




AFFIDAVIT 2002 0155; 1/11/02

2001 4539

FILED RECORDERS OFFICE JONES COUNTY IOWA

01 DEC 26 PM 12: 12

MARIE KRUTZFIELD RECORDER 6.00 Pd



## ) SS COUNTY OF JONES )

- I, Thomas Anthony, depose and state as follows:
- That I am a duly Licensed Land Surveyor licensed and practicing in the State of lowa, with License Number 8295 renewable December 31, 2002; and
- That I executed a survey of and supervised the preparation of certain Section Corner Certificates which were recorded December 26, 2001, as DOCUMENT NO. 2001-4537, 4538 and 4539, Jones County Recorder's Office; and
- 3. That a scrivener's error has been detected on said certificates and in accordance with the provisions of Chapter 354.24, Code of Iowa, the following correction should be substituted for the erroneous data on said certificates:
  - A. In the box on each certificate labeled "Monument Description and Remarks", the section number is mistakenly stated as <u>36</u> when in fact Section <u>35</u> is correct as stated elsewhere on each certificate.
- That the correction stated herein does not affect the locations of the boundaries or the areas depicted on the related plat recorded in Plat Book O - Page 139.