2003 1070 FILED RECORDERS OFFICE JONES COUNTY 10WA

BRIMAR La Du L

			no uak 13			
			MARIE KRI RECOI	JTZFIELD RDER 6.00P	A	
PRE	PARED BY HALL & F	ALL ENGINEERS, INC.	209 29TH STREET	N.E. CEDAR RAPIE	S. (OWA 52402 (319) 3	62-9548
LAN	ID SURVEY MON	UMENTS SITUATE , OF THE FIFTH	D IN SECTION	ات ما	OWNSHIP 85	NORTH,
	RECOVERY TI	<u> DRAWING</u>		MONUMEN	T DESCRIPTION AND	
	-HAILS IN " OWER POLE		нX	COR1/	41/4, SEC.	16, 185N, R4W
4 010	(A65 P.D.)	S7.42 X S7.42 X S7.42 X S7.42 X	COTHER HIDEX	PREVIOUS 8007 ラダエ ソセッタ # リララ4 シレク ムタショ	REPARING CERTIFICATE: PAGE PAGE PAGE PAGE PAGE NITH PED N	L.S. CAP MIERUNE /#ST OF
		1 '				
11.75'_ 42.95'_	S FERCE	251H 105T	CORNELLINDEX	REASON FOR PR PREVIOUS BOOK タピア リケット	EPARING CERTIFICATE: C EPAR WITH PEO FLUSH WITH CE	Q8, C OR D
X-HAILS IN FENCE 185		X-NAILS IN BA				
7	X		CORRER INDEX	REASON FOR PRI	1/4, SEC PARING CERTIFICATE: A	, 8, C OR D
I hereby certify that this land surveying document was prepared and the related survey work was performed by me or under my direct personal supervision and that I am a duly licensed Land Surveyor under the laws of the State of lowa. Date: Date: 2 - 27- Daniel J. Johnson, S. A. 1954 My ticense renewal take is December 31. Pages or sheets covered by this scal:				REASON FOR PREPARING CERTIFICATE: A) THERE IS NO CERTIFICATE FOR THE CORNER ON FILE WITH THE RECORDER OF THE COUNTY IN WHICH THE CORNER IS LOCATED. B) CORNER POSITION DIFFERS FROM THAT SHOWN IN THE PUBLIC RECORDS OF THE COUNTY IN WHICH THE CORNER IS LOCATED. C) THE CORNER MONUMENT HAS BEEN REPLACED OR MODIFIED. D) THE REFERENCE TIES REFERRED TO IN AN EXISTING PUBLIC RECORD ARE INCORRECT OR MISSING.		
	LIC LAND SUR	VEY CORNER C	ERTIFICATE		AND HALL ENG	DINEERS, INC.
	LULA SURVEY			CEDAR	RAPIDS, IOWA 52402 362-9548	
OWN DY.	Checked by.	Approved by:	Field Book No:	Scale: NONE	Dote: Z/12/03	Project No: 4649

SECTION CORNER CERTIFIC	CATE
LAND SURVEY MONUMENTS SITUATED IN SECTION 16, TOWN:	SHIP 85 NORTH, IES , COUNTY, IOWA.
PREVIOUSLY RECORDED IN BOOK AT PAGE	FOR RECORDER'S USE
EASON FOR PREPARING CERTIFICATE: A) THERE IS NO CERTIFICATE FOR THE CORNER ON FILE WITH THE RECORDER OF THE COUNTY IN WHICH THE CORNER IS LOCATED. B) CORNER POSITION DIFFERS FROM THAT SHOWN IN THE PUBLIC RECORDS OF THE COUNTY IN WHICH THE CORNER IS LOCATED. C) THE CORNER MONUMENT HAS BEEN REPLACED OR MODIFIED. D) THE REFERENCE TIES REFERRED TO IN AN EXISTING PUBLIC RECORD ARE INCORRECT.	
MONUMENT DESCRIPTION AND REMARKS: N'4 CORNER SECTION 16- T 85 N- R 4 W CAP # 1/954 ON & COUNTY RO. Z" DEEP 115.30' COUNTY ROAD X-31 S'4 CORNER SECTION 16- T 85 N- R 4 W W/ C.S. CAP # 1/954 FLUSH W/ GROUND	SET Z" REBAR W/L.S. WEST OF & PAVED SET 'Z" REBAR AT FENCE CORNER
RECOVERY TIE DRAWIN	G
COUNTY REBAR X SET 2 SET	• *
I, DANIEL J.JOHNSON CERTIFY THAT THE CORNER LOCATION(S) SHOWN ON THIS RECORD WERE DETERMINED BY ME OR UNDER MY DIRECTION AND CONTROL AND THAT THIS U.S. PUBLIC LAND SURVEY MONUMENT RECORD IS CORRECT AND CONTROL TO THE BEST OF MY KNOWLEDGE AND BELIEF. DANIEL J. JOHNSON L.S. NO 11954 DATE A COVERNMENT CORNER O 5/8 THE PIN SET O THE DOSSING FERICE UNE NO THE PROJECT NO. LINE PROJECT N	Daniel J Johnson 11954 HALL AND HALL ENGINEERS, INC. 226 29TH STREET DRIVE S.E. CEDAR RAPIDS, IOWA 52403 319-362-9548
WR.W.B. & D.T. J. P T. 4-29-92 NONE	F Nº P Nº 46.49

85416c-123092 85421c-123092