UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE SLS1 9-90

OF

Land Survey Monuments situated in Section Three (3 Four (4) West, of the Fifth Principal Meridian, Previously recorded in	in County Recorder's Office.		
(Show reason for preparing this certificate, the evidence and detailed promentation found or placed.) Monument Description and Remarks: No Certificate	•		
rod with RLS Cap No. 8419 in line with f	ound iron rod at N 1/4 Corner		
Section 4 and found stone at S 1/4 Corner S			
of N-S straight section of road south of			
DY ANI YIY			
(Show a minimum of three reference ties to durable physical objects, relerecovery of the corner.)	evant monuments and physical conditions that will enable		
	┍┯┯┯┯┯┯╗╻╻╸┝╼┆╼┰╸┪╸┪		
 			
	┡ ╇ ┦╌┤╌┤╌┤╌┤╌┼╌┤╸┡╼╺╃╸┩╾┋╌╴┃		
+++++++++++++++++++++++++++++++++++++++			
111111111111111111111111111111111111111			
	1		
	EDHEAD MILL		
<u> </u>	Detail Flore		
	SEN VE" ROD		
1 (P) P) P) 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	4/240 0419		
daner	TITITITI W		
" 96 GAAGE TI () TI () TI	-copper		
Garage 1	De Gazage		
DATE OF FIELD WORK: 11/13/91	TSE NO: 91-64		
I hereby certify that the survey work was completed and this certificate	List Corners to be Indexed		
I am a duly registered and surveyor under the laws of the state of	Corners Section Twp Range		
Iowa.	N 1/4 3 86N 4W		
Signature: Name typed or priviled: J David Gibbs			
10g. No. 0413			
11111111111111111111111111111111111111			
J. DAVID	E OF FIELD WORK: 11/13/91 Verify that the Juryey work was completed and this certificate duly registered land surveyor under the laws of the state of N 1/4 3 86N 4W Reg. No. 8419 Reg. No. 8419		
SEAL GIBBS			
α\ 8419 /S			
* * * * * * * * * * * * * * * * * * *			
The Paragraph of the Pa			

Ny 500.3



86403C - 112791

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

OF

	.	mahla	87 North , Range	
Land Survey Monuments situated Four (4) West, of the Fift	in Section 34 The Principal Meridian.	, Township Delaware	County, Iowa.	
Previously recorded in		<u> </u>	n County Recorder's Office.	
(Show reason for preparing this certifica	ige, document number, etc.) te, the evidence and detailed proc	edures used in establishin	g the corner positions and monu-	
mentation found or placed.) Monument Description and Rema	rks: No certificate	of record. Se	t 1/2" dia. iron 🕟	
rod with RLS Cap No. 8	3419 next to found str	one (6" x 6" x 8"	limestone)	_
	·			
4				
	PLAN - VIE	· * * * * * * * * * *	•	
(Show a minimum of three reference tie recovery of the corner.)	s to durable physical objects, rele	vant monuments and phys	sical conditions that will enable	
ecovery of the corner.)				
5 0i	th /4 Coever =	Ferroni 34		
	87 K - RAL	4 .		
	DELLOSOR CO			
	1 9 1		SECTION 34	
"X" NAILS	1 \ 8	"X" MAILS IN	T87N, R4W	A
IN Pauce P	WE S	POWER POLE	•	
			_	Ų .
			<u>-</u>	
			•	
	13	20	•	N
coe	onp			
			-	
Ed. Stone			•	
SET 1/2 B	00 W/4AP		3	W
" <u>8419 4"</u>	DEEP		•	
.301 East			•	
	1 2		<u>-</u>	
	- 0	"" wile is	•	
	<u>' </u>	Bower POLE	-	
	· · · · · · · · · · · · · · · · · · ·			
DATE OF FIELD WORK:	11/13/91	1	TSE NO: 91-64	
I hereby certify that the survey work we	as completed and this certificate		orners to be Indexed	
was prepared by me or under my direct I am a duly registered land surveyor ur	personal supervision and that independent in the laws of the state of	Corners Sect	don Twp Range	
10wa.	<i>\\ \\\</i>	S 1/4 34	87N 4W	
Signature: J. David (Gibbs			
	No. 8419			
	10			
.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	LAND			
or the last	SO			
	. DAVID			
SEAL O	GIBBS S			
α	8419			
Banks .	OWA which	and the second		
*****	(OW P. 1,1,1,1,1			

54 sec. 34 Delawore