Paul H. Helland, 1107 Technology Parkway, Cedar Falls, Iowa 50613-6951, (319)-266-0161 UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE OF _, TOWNSHIP NO. 84 NORTH, RANGE LAND SURVEY MONUMENTS SITUATED IN SECTION NO. 18 COUNTY, IOWA. **JONES** WEST OF THE FIFTH PRINCIPAL MERIDIAN,___ PREVIOUSLY RECORDED IN BOOK 415, PAGE 26 (SHOW REASON FOR PREPARING THIS CERTIFICATE, THE EVIDENCE AND DETAILED PROCEDURES USED IN ESTABLISHING THE CORNER POSITIONS AND MONUMENTATION FOUND OR PLACED.) THIS CERTIFICATE IS FILED TO CORRECT MONUMENT DESCRIPTION AND REMARKS: TOWNSHIP NO. ON 1999 4308 SURVEY DONE IN SE 1/4 NE 1/4 OF SEC. 18-T84N-R4W CENTER: CORNER AS SHOWN IN BK 415 PG 26 WAS SET AT THE INTERSECTION OF LINES BETWEEN THE N 1/4 & S 1/4 CORNERS AND THE W 1/4 & E 1/4 CORNERS, CORNER CERTIFICATE SHOWS CORNER IN LINE WITH FENCE SOUTH, YET FENCE AS LOCATED IN FIELD IS 7.2' WEST OF CORNER. NEW CENTER: FOUND NO. 4 REBAR WITH PINK FLAGGING (0.3' DEEP) 2.75' SOUTH & 7.18' WEST OF CENTER AS LOCATED IN BK 415 PG 26 (NO. 4 REBAR W/SMASHED YELLOW CAP). PLAN VIEW (SHOW A MINIMUM OF THREE REFERENCE TIES TO DURABLE PHYSICAL OBJECTS, RELEVANT MONUMENTS AND PHYSICAL CONDITIONS THAT WILL ENABLE RECOVERY OF THE CORNER.) Centerline Joint County Road E34 SE Comer of Parcel "C" Book 350 Page 209 Found No. 4 Rebar w/smashed yellow cap Corner as per Bk 415 Pg 26 (Recorded As S89°13'25"E 343.28')
—— S89°12'50"E 343.45' 1,68 S89°17'05"E 2666.10' **CENTER** E 1/4 Corner Sec. 18-T84N-R4W 45 "X" Nails in Brace Post ·"X" Nails in Corner Post HELLAND ENGINEERING & SURVEYING, LTD. 1107 Technology Parkway Cedar Falls, Iowa 50613-6951 (319)-266-0161 FILE NAME: 99-279C1.DRG I hereby certify that this land surveying document was prepared ENGINEER and the related survey work was performed by me or under my direct personal supervision and that I am a duly licensed Land LIST CORNERS TO BE INDEXED SECTION TOWNSHIP RANGE CORNER Paul H. Helland Surveyor under the laws of the State of Iowa. PAUL H. CENTER 84N 4W HELLAND 6505 License Number 6505 My license renewal date is December 31, 1999. All pages or sheets are covered by this seal except:

/owa

PREPARED BY HALL & HALL ENGINEERS, INC. 209 29TH STREET N.E. CEDAR RAPIDS, IOWA 52402 (319) 362-9548 SECTION CORNER CERTIFICATE OF

LAND SURVEY MONUMENTS SITUATED IN SECTION 18, TOWNSHIP 84 NORTH, RANGE 4 WEST, OF THE FIFTH PRINCIPAL MERIDIAN, JONE 5. COUNTY, IOWA	
PREVIOUSLY RECORDED IN BOOK AT PAGE	
REASON FOR PREPARING CERTIFICATE: A) THERE IS NO CERTIFICATE FOR THE CORNER ON FILE WITH THE COUNTY IN WHICH THE CORNER IS LOCATED. B) CORNER POSITION DIFFERS FROM THAT SHOWN IN THE PUBLIC COUNTY IN WHICH THE CORNER IS LOCATED. C) THE CORNER MONUMENT HAS BEEN REPLACED OR MODIFIED THE REFERENCE TIES REFERRED TO IN AN EXISTING PUBLIC RE	RECORDS OF THE
MONUMENT DESCRIPTION AND REMARKS:	
NORTH 4 COR. SECTION 18-84-4: FOUND BRASS CAP FLUSH W/ NE COR. SE 4 NW4 SECTION 18-84-4: SET 12 REBAR W/CAP*11954, CENTER OF SECTION 18-84-4: SET 12 REBAR W/CAP*11954, 2"B	FLUSH WITH GROUND ELOW SURFACE
EAST 4 COR. SECTION 18-84-4 FOUND BRIDGE SAKE, REPLACED RECOVERY TIE DRAWING	
NY4 CORNER SECTION 18-84-4 WE COR. WINAILS IN GATE POST SECTION 18-84-4 WE COR. WE COR. WINAILS IN POW. POLE FO. BRASS CAP FLUSH W/ PAVE MENT DRIVE PRORPH CAP #11954 II	SEM NWM SECTION 18-84-4 DITCH. SET 12" ROR XNAILS WICAP # 1954 YEAC. POST
CENTER SECTION 18-84-4 EMC	ORNER SECTION 18-84-4
SET 1/2" RBR WICHP#11954 2" DEEP 47.90' X' NAILS IN COR. POST X' NAILS GATE POST GATE POST	FO. 6DP SPIKE REPLACED WINZ RBR CAP # 11954 2" DEEP
I. DANIEL J. JOHNSON, - CERTIFY THAT THE CORNER LOCATION(S) SHOWN ON THIS REWERE DETERMINED BY ME OR UNDER MY DIRECTION AND CONTROL AND THAT THIS UPUBLIC LAND SURVEY MONUMENT RECORD IS CORRECT AND COMPLETE TO THE BEST KNOWLEDGE AND BELIEF 12-19-96	Daniel J. Johnson 11954
L COVERNMENT CORNER PROPERTY CORNER FOUND O 1/7" X30" W/ LS. CAP STI FIG. PROPERTY LIME PROPERTY LIME HERTZ REAL ESTATE B D ID IC IA IB ISCALE	709 20TH STREET N E CEDAR RAPIDS, IOWA 52402 (319) 367 - 9548
1 3/15/04 SCALL SC	1E 6 5/37