Paul H. Helland, 1107 Technology Parkway, Cedar Falls, Iowa 50613-6951, (319)-266-0161 UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE **OF** LAND SURVEY MONUMENTS SITUATED IN SECTION NO. 18 , TOWNSHIP NO. 84 NORTH, RANGE 4 WEST OF THE FIFTH PRINCIPAL MERIDIAN, JONES COUNTY, IOWA. PREVIOUSLY RECORDED IN BOOK 415, PAGE 26 (SHOW REASON FOR PREPARING THIS CERTIFICATE, THE EVIDENCE AND DETAILED PROCEDURES USED IN ESTABLISHING THE CORNER POSITIONS AND MONUMENTATION FOUND OR PLACED.) THIS CERTIFICATE IS FILED TO CORRECT TOWNSHIP NO. ON 1999 4309 MONUMENT DESCRIPTION AND REMARKS: SURVEY DONE IN SE 1/4 NE 1/4 OF SEC. 18-T84N-R4W E 1/4 CORNER: FOUND NO. 4 REBAR W/RED CAP #11954 (3.7' DEEP) AS PER BOOK 415 PAGE 26, SET NO. 4 REBAR W/ORANGE CAP #6505 ABOVE. NE CORNER: FOUND NO. 4 REBAR W/ORANGE FLAGGING NORTH OF VERY OLD CORNER POST. **PLAN VIEW** (SHOW A MINIMUM OF THREE REFERENCE TIES TO DURABLE PHYSICAL OBJECTS, RELEVANT MONUMENTS AND PHYSICAL CONDITIONS THAT WILL ENABLE RECOVERY OF THE CORNER.) Orange Tag in East Face of Poles to Entryway −No. 4 Rebar w/orange Cap #6505 46 Orange Tag in Top of Post 48.02 10'+/-E 1/4 CORNER Set No. 4 Rebar 0.85'NE CORNER 33.48' County Road E34 Orange Tag in West Face of Very Old Comer Post 10.87 Orange Tag in West Face of Post Orange Tag in West Face of Utility Pole HELLAND ENGINEERING & SURVEYING, LTD. 1107 Technology Parkway Cedar Falls, Iowa 50613-6951 (319)-266-0161 FILE NAME: 99-279C2.DRG I hereby certify that this land surveying document was prepared ENCINEER and the related survey work was performed by me or under my LIST CORNERS TO BE INDEXED direct personal supervision and that I am a duly licensed Land **RANGE** CORNER SECTION TOWNSHIP Surveyor under the laws of the State of Iowa. 15 Harris PAUL H. 4W E 1/4 CORNER 18 84N

NE CORNER

18

84N

4W

HELLAND

6505

AWO1

Paul H. Helland

License Number 6505

My license renewal date is December 31, 1999. All pages or sheets are covered by this seal except: PREPARED BY HALL & HALL ENGINEERS, INC. 209 29TH STREET N.E. CEDAR RAPIDS, IOWA 52402 (319) 362-9548 SECTION CORNER CERTIFICATE OF

LAND SURVEY MONUMENTS SITUATED IN SECTION 18, TOWNSHIP 84 NORTH, RANGE 4 WEST, OF THE FIFTH PRINCIPAL MERIDIAN, JONE 5. COUNTY, IOWA	
PREVIOUSLY RECORDED IN BOOK AT PAGE	
REASON FOR PREPARING CERTIFICATE:  A) THERE IS NO CERTIFICATE FOR THE CORNER ON FILE WITH THE COUNTY IN WHICH THE CORNER IS LOCATED.  B) CORNER POSITION DIFFERS FROM THAT SHOWN IN THE PUBLIC COUNTY IN WHICH THE CORNER IS LOCATED.  C) THE CORNER MONUMENT HAS BEEN REPLACED OR MODIFIED  THE REFERENCE TIES REFERRED TO IN AN EXISTING PUBLIC RE	RECORDS OF THE
MONUMENT DESCRIPTION AND REMARKS:	
NORTH 4 COR. SECTION 18-84-4: FOUND BRASS CAP FLUSH W/ NE COR. SE 4 NW4 SECTION 18-84-4: SET 12 REBAR W/CAP*11954, CENTER OF SECTION 18-84-4: SET 12 REBAR W/CAP*11954, 2"B	FLUSH WITH GROUND ELOW SURFACE
EAST 4 COR. SECTION 18-84-4 FOUND BRIDGE SAKE, REPLACED RECOVERY TIE DRAWING	
NY4 CORNER SECTION 18-84-4  WE COR.  WINAILS IN GATE POST  SECTION 18-84-4  WE COR.  WE COR.  WINAILS IN POW. POLE  FO. BRASS  CAP FLUSH  W/ PAVE MENT  DRIVE  PRORPH  CAP #11954  II	SEM NWM SECTION 18-84-4  DITCH.  SET 12" ROR XNAILS WICAP # 1954 YEAC. POST
CENTER SECTION 18-84-4 EMC	ORNER SECTION 18-84-4
SET 1/2" RBR WICHP#11954 2" DEEP  47.90'  X' NAILS IN COR. POST  X' NAILS GATE POST  GATE POST	FO. 6DP SPIKE  REPLACED WINZ RBR  CAP # 11954  2" DEEP
I. DANIEL J. JOHNSON, - CERTIFY THAT THE CORNER LOCATION(S) SHOWN ON THIS REWERE DETERMINED BY ME OR UNDER MY DIRECTION AND CONTROL AND THAT THIS UPUBLIC LAND SURVEY MONUMENT RECORD IS CORRECT AND COMPLETE TO THE BEST KNOWLEDGE AND BELIEF    12-19-96	Daniel J. Johnson 11954
L COVERNMENT CORNER PROPERTY CORNER FOUND O 1/7" X30" W/ LS. CAP STI FIG. PROPERTY LIME PROPERTY LIME HERTZ REAL ESTATE  B D ID IC IA IB ISCALE	709 20TH STREET N E CEDAR RAPIDS, IOWA 52402 (319) 367 - 9548
1 3/15/04 SCALL SC	1E 6 5/37