
RECORDERS OFFICE JONES COUNTY IOWA

05 JAN 21 AM 9: 59

MARIE KRUTZFIELD RECORDER 700 pd

PREPARED BY HALL & HALL ENGINEERS, INC. 209 29TH STREET N.E. CEDAR RAPIDS, IOWA 52402 (319) 362-9548



U.S. PUBLIC LAND SURVEY CORNER CERTIFICATE LAND SURVEY MONUMENTS SITUATED IN SECTION 100, TOWNSHIP 83 NORTH, RANGE 4 WEST, OF THE FIFTH PRINCIPAL MERIDIAN, 100 COUNTY 10WA.

REASON FOR PREPARING CERTIFICATE:

- THERE IS NO CERTIFICATE FOR THE CORNER ON FILE WITH THE RECORDER OF THE COUNTY IN WHICH THE CORNER IS LOCATED.
- CORNER POSITION DIFFERS FROM THAT SHOWN IN THE PUBLIC RECORDS OF THE COUNTY IN WHICH THE CORNER IS LOCATED.

 THE CORNER MONUMENT HAS BEEN REPLACED OR MODIFIED.
- C)
- THE REFERENCE TIES REFERRED TO IN AN EXISTING PUBLIC RECORD ARE INCORRECT OR MISSING. D)



I hereby certify that this land surveying document was prepared and the related survey work was performed by me or under my direct personal supervision and that I am a duly licensed Land Surveyor under the laws of the State of Iowa.

Daniel J. Johnson 1, 3, 11954 My license renewadiate is December 31, 2006 <u>1-20-05</u>

Date

1) Hav. GOR. SEC. 16-83-4, Fp. S.C. M. Z-O DEEP SET S/B" IRON PINT ON SOUTH FACE OF MONUMENT 51.64' 38.82 34.98 - True 50TH ST. NOTE: ALL TIES FO. NAIL IN TOP OF FENCE POSTS 83417e 12005. 40 (2) H.1/4 COR. SEC. 16-83-4, FD. BROKEN OFF 5.6.14. 2.0' PEEP 2'T HOUTH OF CENTERLINE RO. IN LINE WITH FEACE SOUTH, SET 1/2"
REGAR ON SOUTH FACE OF MONUMENT 12525 HALL AND HALL DISK.
IN TOP OF CEDAR BOT 31.62 SOTH 57. 39.59 35.79 HALL AND HALL DISK IN TOP OF CATE POST HALL NO HALL DISK IN TOP OF ERACE TOP OF BUS FOST 012005-46

3 N.E. COR., SEC. 16-83-4, FD. BROKEN OFF S.C.M. 18" DEEP 0.2" SOUTH OF EAST-WEST FENCE, SET 1/2" MENOR ON SOUTH FACE OF MONUMENT 935 48.38 48.13 26.99 834/160-012005 TIE

4 5.1/4 CORNER, SEC. 16-83-4 FD. S.G.M. ABOVE SURFACE ON EAST. WEST FENCE Z'EAST OF NORTH - SOUTH FENCE, SET 1/2" REBAR ON NORTH FACE OF MONIDMENT 1259 < 10.23 15.85 4-19-834/2/cf 012005.70 NOTE: SET HALL AND HALL SURVEY DISKS

HIEHAUS

Scale: Date: ム/さッ/oろ Project No: ield Book No: Drawn by: Approved by: に入し Checked by: ワン)

2000 3927 FILED RECORDERS OFFICE

JONES COUNTY IOWA 00 DEC 27 PM 3: 31

MARIE KRUTZFIELD RECORDER 6.00 pd

CLARENCE J. WALTON, LS # 11310, WALTON LAND SURVEYING, P.C., 2213 LAUREN DR. SW, CEDAR RAPIDS, 10WA 52404, (319) 363-4271 UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE LAND SURVEY MONUMENTS SITUATED IN SECTION 9, TOWNSHIP 83 NORTH, RANGE 4 WEST OF THE 5TH PRINCIPAL MERIDIAN, JONES COUNTY, IOWA Ν SE CORNER SW CORNER ALL TIES: FOUND SPIKE IN TOP OF WOOD FENCE POST. ALL TIES: SET NAIL IN TOP OF WOOD FENCE POST 35.16 51.63 66.2>, 47.01° 26.48 27.67 48.61 50TH STREET 50TH STREET AVENUE 230TH 1 : STEEL FENCE POST MONUMENT DESCRIPTION AND REMARKS MONUMENT DESCRIPTION AND REMARKS 1/2" REBAR 8" DEEP FROM PREVIOUS SURVEY. FOUND LEANING SCM 6" SOUTH OF EAST-WEST FENCE LINE. NOTE: ALL MEASUREMENTS IN FEET AND DECIMALS THEREOF. ME CLARY I hereby certify that this land surveying document and the related survey work was performed by me or under my direct personal supervision and that I am a duly licensed Land Surveyor under the laws of the State of lowa.

Signed

Date CORNERS TO BE INDEXED CORNERS SECTION RANGE CLARENCE SW 83N SE Clarence J. Walton, L.S.
Wy License Renewal Date is December 31, 2001
License Number 11310
Pages or sheets covered by this seal: WALTON 12/27/00 11310 ROJECT WALTON LAND SURVEYING, P.C. UNITED STATES
PUBLIC LAND
SURVEY CORNER 2 CJW 2213 LAUREN DRIVE SW NO: CEDAR RAPIDS, IOWA 52404 12/26/00 NONE

(319) 363-4271

 $\overline{\omega}$

CERTIFICATE

SECTION CORNER CERTIFICATE				
OF LAND SURVEY MONUMENTS SITUATED IN SECTION 17, TOWNSHIP 83 NORTH, RANGE 4 WEST, OF THE FIFTH PRINCIPAL MERIDIAN, Jones, COUNTY, IOWA.				
PREVIOUSLY R	ECORDED IN BOOK	AT PAG	GE	FOR RECORDER'S USE
REASON FOR PREPARING CERTIFICATE: X A) THERE IS NO CERTIFICATE FOR THE CORNER ON FILE WITH THE RECORDER OF THE COUNTY IN WHICH THE CORNER IS LOCATED. B) CORNER POSITION DIFFERS FROM THAT SHOWN IN THE PUBLIC RECORDS OF THE COUNTY IN WHICH THE CORNER IS LOCATED. C) THE CORNER MONUMENT HAS BEEN REPLACED OR MODIFIED. X D) THE REFERENCE TIES REFERRED TO IN AN EXISTING PUBLIC RECORD ARE INCORRECT.				
MONUMENT DESCRIPTION AND REMARKS: Dug & found S.C.M. along foreslope of road. Marker has been broken into 3 pieces. Staked back together and set 5/8x24" Iron Pin on top of monument pin 1 ft. below. The surface marker is 4 ft. West of the North fence line and 34.5 ft. South of the R.O.W. fence.				
RECOVERY TIE DRAWING				
NE Corner 17-8. FENCE POSTS A B CO	GORNER POST	NOT TO SCALE		GREEN FIELD NE COR SEC.17 ON CARD 12-6-90 M.S.
I, GLEN D. MEISNER, - CERTIFY THAT THE CORNER LOCATION(S) SHOWN ON THIS RECORD WERE DETERMINED BY ME OR UNDER MY DIRECTION AND CONTROL AND THAT THIS U.S. PUBLIC LAND SURVEY MONUMENT RECORD IS CORRECT AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF. A COVERNMENT CORNER O 5/8" HE PIN STI CENTERINE U.S. PUBLIC LAND SURVEY RECORD HALL AND HALL ENGINEERS, INC. 226 29TH STREET DRIVE S.E. CEDAR RAPIDS, IOWA 52403 119-362-9548				
		Ž.	BCALE	319-362-9548
N	K	<u>l</u>	<u> </u>	3

00000 11179x