UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

LAND SURVEY MONUMENTS SITUATED IN SECTION _31_, TOWNSHIP _83_ NORTH RANGE _4_ WEST OF THE 5TH P.M., ______JONES_____ COUNTY, IOWA. SE CORNER S 1/4240TH AVENUE FOUND X'D NAILS IN FENCE CORNER FOUND X'DY NAILS IN POWER POLE 19.90 FOUND X'D FOUND X'D NAILS IN POWER POLE NAILS IN POWER POLE CEDAR-JONES ROAD CEDAR-JONES ROAD 52.57 52.781 AVENU FOUND X'D NAILS IN FENCE POST TOP OF TELEPHONE PEDESTAL CLARENCE WALTON 11310 PREVIOUSLY RECORDED IN BOOK __ PREVIOUSLY RECORDED IN BOOK _____ PAGE ___ MONUMENT DESCRIPTION AND HOW ESTABLISHED __ MONUMENT DESCRIPTION AND HOW ESTABLISHED ____ FOUND 1" REBAR 8" BELOW SURFACE FOUND BROKEN MONUMENT 8" DEEP IN DITCH. BONE DONE CORNERS TO BE INDEXED TOWNSHIP SECTION I hereby declare that this plat, survey or report was made by me or under my direct personal supervision and that I am a duly registered Land Surveyor under the laws of the State of Iow Signed

Date CORNER R4W S 1/4 31 R4W SE CORNER T83N BRAIN ENGINEERING, INC. Clarence J. Walton L.S. Iowa Reg No. 11310

My Registration Renewal Date Is December 31, 1999 777 10TH STREET

MARION, IOWA **5230**2 (319) 373-1318

23289-10