

FEEBOOK: 2007 0096 1/9/2007 11:27 AM

REC FEES: \$7.00

PAGES: 1

Marie Krutzfield, Recorder Jones County, Iowa


(319) 294-9424

PREPARED BY

STEPHEN MICHAEL BRAIN, BRAIN ENGINEERING, INC., 1540 MIDLAND COURT NE, CEDAR RAPIDS, IOWA PH. (319) 294-9424

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

LAND SURVEY MONUMENTS SITUATED IN SECTION $\frac{33}{}$, TOWNSHIP $\frac{83}{}$ NORTH RANGE $\underline{4}$ WEST OF THE 5TH P.M., $\underline{}$ JONES _____ COUNTY, IOWA.



PREPARED BY HALL & HALL ENGINEERS, INC. 209 29TH STREET N.E. CEDAR RAPIDS, IOWA 52402 (319) 362-9548 SECTION CORNER CERTIFICATE			
LAND SURVEY MONUMENTS SITUATED IN SECTION 34, TOWNSHIP 83 NORTH,			
RANGE 4 WEST, OF THE FIFTH PRINCIPAL MERIDIAN, JONES. COUNTY, IOWA.			
PREVIOUSLY RECORDED IN BOOK AT PAGE			
REASON FOR PREPARING CERTIFICATE: A) THERE IS NO CERTIFICATE FOR THE CORNER ON FILE WITH THE RECORDER OF THE			
COUNTY IN WHICH THE CORNER IS LOCATED. B) CORNER POSITION DIFFERS FROM THAT SHOWN IN THE PUBLIC RECORDS OF THE COUNTY IN WHICH THE CORNER IS LOCATED.			
C) THE CORNER MONUMENT HAS BEEN REPLACED OR MODIFIED D) THE REFERENCE TIES REFERRED TO IN AN EXISTING PUBLIC RECORD ARE INCORRECT			
MONUMENT DESCRIPTION AND REMARKS:			
HTA COR. SEC. 34-83-4: SET 12" REBAR WICAP # 11954 2" DEEP, &- & 15THST, \$ 220TH AVE.			
E "4 COR. SEC. 34-83-4: SET "2" REBAR W/CAP # 11954 3" DEEP, 2'WEST OF & CHERRY GROVE RA & 5'NORTH OF & 15THST.			
RECOVERY TIE DRAWING			
WY4 CORNER SECTION 34-83-4		E'Y CORNER	SECTION 34-83-4
² y 1 13.3	4 3 4 4	'X'NAILS IN	
X'NAILS IN TO R.D.W.		Pow. Poce of	X NAILS IN
"X' NAILS IN ROW. RAIL SET 12" ROR SET 12" ROR	49	67.4	2' COR. POST
W/CAP = 11954		£ 15 TH ST.	13 FIELD DRIVE
)\ = 37 EE1 CAR.		89.31	F. F.
O X'NAULS IN		SET WICA	WIRDR X'NAILS IN
POW. POLE 37A. 321		'X'NAILS IN ENO POST	Pow. Pore
Green Field			
7-0			
$\Gamma = e^{\ell \Gamma}$	LA .		
	-∞0 ∞-		
	1		
I DANIEL I JOHNSON, CERTIFY THAT THE CORNER LOS			
I, DANIEL J. JOHNSON, - CERTIFY THAT THE CORNER LOC WERE DETERMINED BY ME OR UNDER MY DIRECTION AND PUBLIC LAND SURVEY MONUMENT RECORD IS CORRECT	D CONTROL AND TH	AT THIS II S	
PUBLIC LAND SURVEY MONUMENT RECORD IS CORRECT AND COMPLETE TO THE BEST OF BY KNOWLEDGE AND BELIEF			
DANIEL J. JOHNSON L.S. NO. 11954 DATE			
83433 ₀ _ 102797			
MY LICENSE RENEWAL DATE IS DECEMBER 31, 1938 834340 _ 102797			
L & COMERNMENT CORNER E O PROPERTY CORNER FOUND G O 1/7" X30" W/ LS CAP STT HALL AND HALL ENGINEERS, INC.			
209 20 TH STREET N.E. PROPERTY LINE MECHANICS VILLE TO TO THE TO THE CEDAR RAPIDS, 10WA 52402			
TE NUMP H JSR	1 4/19/94	SCALI	HE 100