
UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

Monument Description and Remarks: CORNER - FD. 1/2" IRON ROD W/RED MARRED LS	S CAP
NE CORNER	VIEW
FD. 1/2' IRON ROD W/ POWER POLE REB MARRED LS CAP JUNGLE TOWN RD. 94.42'	
34.66' X X CURNER PUST PUST SET NAIL W/ WITNESS DISK AT ALL TIE POINTS	
	CORNERS TO BE INDEXED
24	NE CORNER 24 83N 2W
SEC. 24 TWP. 83N RANGE 2W	



I	hereby	certify	that t	his land	surveying	document	was ,	orepared
ai	nd relat	ed surve	y work	was pe	rformed by	/ me or ui	nder i	my direct
_	onconal	cunantic	ion and	$t + h_0 + I$	am a duly	liconcod I	and	Cunuauan

under the laws of the State of Iowa.

William H. Burger

License number 12642

My license renewal date is December 31, 2010 Pages or Sheets covered by this seal: Sheet 1 of 1

	ì							
SECTION CORNER CERTIFICATION OF LAND SURVEY MONUMENTS SITUATED IN SECTION 19. TOWNS RANGE 1 WEST, OF THE FIFTH PRINCIPAL MERIDIAN, JONE	SHIP 83 NORTH,							
PREVIOUSLY RECORDED IN BOOK AT PAGE	FOR RECORDER'S USE							
REASON FOR PREPARING CERTIFICATE: A) THERE IS NO CERTIFICATE FOR THE CORNER ON FILE WITH THE RECORDER OF THE COUNTY IN WHICH THE CORNER IS LOCATED. B) CORNER POSITION DIFFERS FROM THAT SHOWN IN THE PUBLIC RECORDS OF THE COUNTY IN WHICH THE CORNER. IS LOCATED. C) THE CORNER MONUMENT HAS BEEN REPLACED OR MODIFIED. D) THE REFERENCE TIES REFERRED TO IN AN EXISTING PUBLIC RECORD ARE INCORRECT.								
MONUMENT DESCRIPTION AND REMARKS: N.W. CORNER SECTION 19-T83N. RIW SET # 11954 ON & TUNGLE COUNTY ROAD Z N'4, CORNER SECTION 19-T83N- RIW SET 12 # 11954	" DEEP							
RECOVERY TIE DRAWING								
N.W. Cor. 19-83-1 N'4 Cor. 19-83-1								
X: NOILS	8/594 18 Tree x nails 55' North to 71.00 71.00 12' Clump of Small Trees							
O S O S O S O S O S O S O S O S O S O S	7.80 7.80 7.80 7.80 7.80 7.80 7.80 7.80 7.80 7.80 7.80 7.80 7.80 7.80 7.80 7.80 7.80 7.80							
83119 - 081394 X NAIL IN BR. POST X Field	42" Cotton wood							
ON CORD NE CORNER SEC. 34 783 N R2 W 1. DANIEL J.JOHNSON. CERTIFY THAT THE CORNER LOCATION(S) SHOWN ON THIS RECORD WERE DETERMINED BY ME OR UNDER MY DIRECTION AND CONTROL AND THAT/THIS U.S. PUBLIC LAND SURVEY MONUMENT RECORD IS CORRECT AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF. DANIEL J. DHNSON L.S. NO 11954 DATE								
A COVERNMENT CORNER O 5/8" TE PIN SET O 5/8" TE P	HALL AND HALL ENGINEERS, INC. 226 29TH STREET DRIVE S.E. CEDAR RAPIDS, IOWA 52403 319-362-9548							
RWB RDJJ F P 3.2-93 SCALE NONE	от 27 9 47.16							

13224e=08151911-19-94

6

DN land