2006 0027 RECORDERS OFFICE JONES COUNTY TOWA

06 JAN - 3 PM 12: 50


MARIE KRUTZFIELD

RECORDER 7.00 Pd Prepared by: Richard M. Kordick, P.E.L.S., 120 East Main, Suite D, Anamosa, IA 52205 Phone: (319) 462-4498 U.S. PUBLIC LAND SURVEY CORNER CERTIFICATE Set 1/2" rebar, 4" high Set 1/2" rebar, 4" high on 5. side of power pole on 5. side of power pole-32-85N-2W Jones County SCOTCH GROVE Township Found 5/8" rebar, 3" deep-5 1/4 Corner Section 32-85-2 Found 5/8" rebar, 3" deep 130th Street Set 1/2" rebar, 4" high on N. side of power pole 85232 No Scale Section corner location: S I/4 Corner, Section 32-85-2 Reason for corner tie: ■A)There is no certificate for the corner on file with the recorder. □B)Corner position differs from previously recorded certificate recorded in book , page □C)Corner monument was replaced or modified. D)Reference ties in previously recorded certificate recorded in book , page are incorrect or missing. Research at the recorder's office, auditor's office, and engineer's office revealed the following: No information was found. Field search performed was as follows: Field search was performed with a metal detector and excavation. Monument found or set: A 5/8" rebar, 3" deep, was found and used as the corner.



I hereby certify that this land surveying document was prepared and the related survey work was performed by me or under my direct personal supervision and that n a duly licensed I and Gungayor under the laws of

LEGEND:



THIS IS NOT A CERTIFICATION

JONES COUNTY ENGINEER'S OFFICE, 19501 HWY. 64, ANAMOSA, IOWA, 52205 (319)462-3785

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

LAND SURVEY MONUMENTS SITUATED IN SECTION 32, TOWNSHIP 85 NORTH, RANGE 2 WEST OF THE 5TH P.M., JONES COUNTY, IOWA

