UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

OF

Land Survey Monuments situated in Section Eight (8), of the Fifth Principal Meridian,	, Township <u>86 North</u> , Range
Previously recorded in Book, Page	county, lowa.
(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.) Monument Description and Remarks:No certificate recorded in Recorder's Office.	
Found iron pipe with RLS Cap No. 2435,	see Book H, Page 82.
	No.
PLAN - VII	DYX7
(Show a minimum of three reference ties to durable physical objects. released over the corner.)	evant monuments and physical conditions that will enable
	Sec. 8, T86N
	RIW
	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
	700
	6
	\\ \\ \
5/4 COR. SEC. 8, T86N, RIW -	
FOUND IRON PIPE W/ RLS CAP NO. 2435	26 36'/FLORE CHAMED
RES CAP NO. 2483	6.36 (SLOPE CHAINED)
17.72' 9.34'	
11 11 11 11	297 ± 1
"X" NAILS IN	COR. POST
WD. FENCE POST	WASH-
	N 1/4 cor so
	10 14 COR 580
	ON CARD
	12-21-90
	M.S.
DATE OF FIELD WORK: September 21, 1990	TSE NO. 90-02
hereby certify that the survey work was completed and this certificate as prepared by me or under my direct personal supervision and that	List Corners to be Indexed
am a duly registered land surveyor under the laws of the state of	
owa.	Corners Section Twp Range
Kogn R. Moha September 25/990	S 1/4 8 86N 1W N 1/4 17) 86N 1W
REGISTERED LAND SURVEYOR NO. 10165	1W
EAL SURVE	

ROGER R. MOHN