
UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

OF

and Survey Monuments situated in Section 1 West, of the Fifth Principal Mer	8	Towns	ship <u>8</u>	6 North	, Range
1 West , of the Fifth Principal Mereviously recorded in Book	ndian,, Page	ones	Co 	unty, Iowa.	
ow reason for preparing this certificate, the evidence an nation found or placed.) onument Description and Remarks: Found					
foot deep. No certificate pre					
ld corner ties accessories non-	existent				
PL	AN - VII	E W			
now a minimum of three reference ties to durable physical overy of the corner.)	al objects. rele	evant monuments	and physic	al conditions that	will enable
"X" NAILS IN FENCE POST				Sec. 8, T8	6N
,0·\0				R1W	
FOUND STONE 5.50' WIRON BAR					
	•			W	45H. 14 COR SO
GATE		IAILS IN		E	4 COR S
	GA7	E POST	- -		CAKD
				12-2	•
				/ч.	S .
Date of Field Work: March 6,	1990			TSE No.	90-02
creby certify that the survey work was completed and this prepared by me or under my direct personal supervision maduly registered land surveyor under the laws of the s	n and that		List Corne	rs to be Indexed	
Pan R. Nola September ?		Corners W 1/4 E 1/4	Section 8	Twp 86N 86N	Range 1 W 1 W

SEAL



THIS IS NOT A CERTIFICATION



JONES COUNTY ENGINEER'S OFFICE, 19501 HWY. 64, ANAMOSA, IOWA, 52205 (319)462-3785

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

LAND SURVEY MONUMENTS SITUATED IN SECTION 7, TOWNSHIP 86 NORTH, RANGE 1 WEST OF THE 5TH P.M., JONES COUNTY, IOWA

