UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

OF

Land Survey Monuments situated in SectionEight (8) , Township 86 North , Range Jones County, Iowa.
reviously recorded in Book, Page	;
Show reason for preparing this certificate, the evidence and detailed propertation found or placed.) Monument Description and Remarks: No certificate	
Found iron pipe with RLS Cap No. 2435,	
todia from proc with Rib cap No. 2505,	' rage oa.
	-
PLAN - VI	FXV
Show a minimum of three reference ties to durable physical objects, rele	evant monuments and physical conditions that will enable
ecovery of the corner.)	
	Sec. 8, T86N
	R1W
ang kalang ang kalang kala	
\mathcal{A} ,	
	724
NO PIPE W/R	20N)
PIPE W/R CAP. NO ZA	435 \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
	ROW RAIL
ROW RAIL / 3/1.59'	
	4
ROW X	ZAIL 2 1 0
JOHN MORIAR	VITY
"JOHN MORIAR PLACE", BK.H,	P.BZ m
	FOUND IRON PIPE W/RLS CAP NO 2435
	W/ XZS ESII NO Z433
DATE OF FIELD WORK: March 6, 1990	TSE NO. 90-02_
DATE OF FIELD WORK: March 6, 1990	13E NO. 90-02
hereby certify that the survey work was completed and this certificate	List Corners to be Indexed
as prepared by me or under my direct personal supervision and that am a duly registered land surveyor under the laws of the state of	
owa.	Corners Section Twp Range
Lage & MhD Sontanho X 1990	NE of SW4 SW4 8 86N 1W
DATE	SE of NW ₄ SW ₄ 8 86N IW
REGISTERED LAND SURVEYOR NO. 10165	NW of SE ¹ ₄ SW ¹ ₄ 8 86N 1W WAS SW of NE ¹ ₄ SW ¹ ₄ 8 86N 1W
SURVA	OON IW /
EAL	
REGISTERED	
ROGER R.	ON CARD
МОНИ	