UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

OF

Land Survey Monuments situated in Section 2	, Township84N, Range
, of the Fifth Principal Meridian,	Jones County, Iowa. ***********************************
(book page document number etc.)	
(Show reason for preparing this certificate, the evidence and detailed preparation found or placed.)	
Monument Description and Remarks: Section cor	
	owners had dozed the fence line ane
destroyed the corner. Set 3/4" x	24" iron rod at recorded distances
in the Engine	eer"s office. Corner is in the new
fence line and flush with the grour	nd.
PLAN - V	IEX
(Show a minimum of three reference ties to durable physical objects, re-	
recovery of the corner.)	Sec. 2
Red Top in fence post	\ \ \ \ \ \-
	/n ut
Red Top	
Tree	
# 48.b	RIW
ELY Cor. Sec. 2, 784N 0.60.	A .
P/W-Cor. 15 Red 10pm	
0.3' West of france 1851 fence-flush	
w/ground	
	
$\downarrow_{\hat{o}}$	N
± 1	
	\
6	D. Michael
· · · · · · · · · · · · · · · · · · ·	Filed 3/18/91
	en e
Sta. 288	+04.59
d G. Rd	
Not To Scale	
I hereby certify that the survey work was completed and this certificate	
was prepared by me or under my direct personal supervision and that	List Corners to be Indexed Corners Section Twp Range
I am a duly registered land surveyor under the laws of the state of lowa.	E ¹ 4 2 84N 1W
Signature: William D. Upmeyer	
Name typed or printed: William D. Upmeyer	
Date: 8-29-91 Reg. No. 2869	
ER. E. LAWS	
WILLIAM D.	
SEAL UPMEYER : ON	
NO. 2869 →	
2000	
OWA	
Whitesam	